## **POSTPROCESS DETERGENT RENUMBERING KEY**

Material - Technology - Process

PLM = Polymer MTL = Metal AUX = Auxiliary

100 series = PolyJet 200 series = FDM 300 series = MJF 400 series = Resins

g)	/ - Proc	ess
	Support & Resin Removal	CENTI* FORTI DEMI
	Support Removal	DECI BASE
	Surface Finish	RADOR LEVO* NITOR
	Hybrid/ Multiple	DECI DUO
	Supple- mental	Auxiliary

OLD		NEW	
PG1	=	PLM-101-SUB	PolyJet
PG2	=	PLM-201-SUB*	FDM
PG2.1	=	PLM-202-SUB*	
PG1.1	=	PLM-401-SUB	
PG1.2	=	PLM-402-SUB	Resin
PG1.3	=	PLM-403-SUB*	
PG1C Part A	=	PLM-101-SPRAY	PolyJet
PG1C Part B	=	PLM-102-SPRAY	Polyset
PG2C Part A	=	PLM-201-SPRAY	
PG2C Part B	=	PLM-202-SPRAY	FDM
PG2C Part C	=	PLM-203-SPRAY	
PG1.1C Part A	=	PLM-401-SPRAY	Resin
PG1.1C Part B	=	PLM-402-SPRAY	
PG3	=	PLM-001-SURF	
PG5	=	PLM-001-DUO	
PG7.1	=	AUX-001-DEFOAM	
PG7.2	=	AUX-002-DEFOAM	
PG7.3	=	AUX-003-DEFOAM	
Duo Clean	=	AUX-001-CLEAN	
PGN	=	AUX-001-NEU	

